

SAFETY-RELATED VEHICLE RECALLS

Vehicle manufacturers are required to mail a recall notice to all purchasers, owners and dealers when a safety defect or noncompliance with Federal safety standards is found.

This notice identifies the year, make, engine(s) and other information related to the vehicle(s) involved with this recall, along with a brief description of the problem, and other pertinent information. Not all vehicles of a particular year, make and model may be subject to the recall. Contact the manufacturer or one of the manufacturer's dealers with any questions regarding this recall.

RECALL NOTICE SUMMARY

Manufacturer: ROLLS-ROYCE MOTORS, INC.
Campaign Number, Case: 02V187000,
Defect Report:
Recall Initiator: MFR
Dates: 1/1/1998-5/31/2002
Date Owner Notified: 7/19/2003
Vehicles: 1999-2002 BENTLEY ARNAGE, 1999-2002 BENTLEY ARNAGE LE MANS, 1999-2004 BENTLEY ARNAGE LIMOUSINE, 1999-2002 BENTLEY ARNAGE LWB, 1999-2002 BENTLEY LIMOUSINE, 1999-2002 ROLLS ROYCE PARK WARD, 1999-2002 ROLLS ROYCE SILVER SERAPH, 1999-2002 ROLLS ROYCE SILVER SERAPH LOL
No. Vehicles Recalled: 66720
Noncompliance: ON CERTAIN PASSENGER VEHICLES AND LIMOUSINES, THE LOW PRESSURE BRAKE FLUID FEED PIPE BETWEEN THE MASTER CYLINDER AND REMOTE RESERVOIR HAS THE POTENTIAL TO TRAP OR RETAIN AIR.
Consequence: THIS AIR COULD ENTER THE MASTER CYLINDER CAUSING EXCESSIVE PEDAL TRAVEL AND PARTIAL FAILURE OF THE PRIMARY CIRCUIT, INCREASING THE RISK OF A CRASH.
Corrective Action: DEALERS WILL REPLACE BOTH HOSES AND BRAKE FLUID RESERVOIR. OWNER NOTIFICATION BEGAN JULY 19, 2002. OWNERS WHO TAKE THEIR VEHICLES TO AN AUTHORIZED DEALER ON AN AGREED UPON SERVICE DATE AND DO NOT RECEIVE THE FREE REMEDY WITHIN A REASONABLE TIME SHOULD CONTACT ROLLS-ROYCE AT 1-800-777-6923.

This recall summary reflects information submitted by the vehicle manufacturer. While it is an accurate reflection of the information submitted, the NHTSA and/or the vehicle manufacturer may make changes at any time. No warranty, expressed or implied, is made as to its accuracy or completeness, nor is any responsibility assumed by Tecfacts Services, LLC. for loss, damages (direct or indirect), consequential or compensatory, including without limitation, lost profits, breaches or defaults caused by reliance on the information in this summary.

Copyright © Tecfacts Services, LLC 2004. All rights reserved. No portion of this document may be reproduced, copied, transmitted, distributed or stored, by any means, in any form electrical or mechanical, including recording or by any information storage or retrieval system without written permission.